

Snowpit in the crown of an avalanche that occurred on Saturday (1/5) near Ross Peak. Likely triggered by a snowmobiler as they rode downhill on an adjacent slope. link below for more details. Photo: GNFAC

Advisory Region
Bridger Range
Avalanche Details: Avalanche near Ross Peak/Throne
Bridger Range, 2019-01-07