

From obs: "On Sunday morning, the sun broke through for a bit and allowed us to view the widespread avalanche cycle that occurred overnight on all aspects. Across the creek, we saw a large crown (approx 3’ in depth) in the meadows.

An avalanche that occurred on Nemesis’s south face ran from mid-mountain all the way into Hellroaring Creek, running over our old skin track." Photo: Eric and Melissa

Advisory Region

Island Park
Longitude
-111.48W
Latitude
44.55N
Avalanche Details: Natural slides on all aspects of Nemesis Mountain
Island Park, 2023-04-04