

Our snowpit showed instability in the small, sugary facets that are underneath a hard slab of wind blown snow. An avalanche was triggered around the corner from this snowpit around the same time we were digging! Photo: GNFAC

Advisory Region
Northern Madison
Longitude
-111.40W
Latitude
45.18N

Avalanche Details: Snowmobiler triggered wind slab on Buck Ridge
Northern Madison, 2018-12-16