

"We came across the debris of a significant slide in one of the steeper lines just north of Wolverine bowl today. There was zero new fallen snow on the debris so it happened sometime this morning before 11:30 a.m. and after the snowfall stopped last night. The multiple crowns looked to be 3-5 feet tall and a large tree has been jammed into the tube ride chute. The toe of the debris is all the way down into the creek at the base of Wolverine. It's possible a large cornice broke off at the ridgeline but we couldn't get eyes on the actual start of the slide. We skinned up and down the debris pile twice while in search mode at around 12:30 but did not pick up a signal. We did not investigate above the pinch of the chute and into the upper part of the slide. The debris pile is quite deep

with some damaged trees. We did 6 lines off the ramp over the weekend and did not see any other avalanche activity but obviously some significant wind loading." Photo: Ray K

Advisory Region
Bridger Range
Longitude
-110.93W
Latitude
45.83N
Avalanche Details: Wolverine Bowl natural avalanche, Bridgers
Forecast link: GNFAC Avalanche Forecast for Mon Feb 17, 2020
Bridger Range, 2020-02-16