

From obs: "triggered a small wind slab in sluice box today. this was not a surprise as all of the wind loaded areas had shown cracking and instability on the way up. though these other areas exhibited the same instability, this little pocket in sluice was the only spot steep enough to run. wanted to stop and measure slope angle but the dog was getting cold"

Photo: J. Armer

Advisory Region

Bridger Range
Longitude
-110.92W
Latitude
45.82N
Avalanche Details: Wind slabs mid-slope at Bridger Bowl
Forecast link: GNFAC Avalanche Forecast for Sat Nov 19, 2022GNFAC Avalanche Forecast for Sun Nov 20, 2022
Bridger Range, 2022-11-18