

We noted four storm slab avalanches along Lionhead Ridge and two larger slides that broke deeper on wind loaded slopes. Photo: GNFAC

Advisory Region
Lionhead Range
Longitude
-111.32W
Latitude

44.73N

Forecast link: GNFAC Avalanche Forecast for Fri Mar 8, 2024
Lionhead Range, 2024-03-07