

My partner and I were approaching Responsible FamilyMan via Avalanche Gulch early yesterday morning (3/18), and once we broke through the trees into the runout zone, we stumbled across a pretty large wet avalanche debris field. The debris terminated within ~50 yards of the max runout zone. Photo: R. Parsons

Advisory Region
Northern Gallatin
Longitude
-110.96W

Latitude
45.45N

Forecast link: GNFAC Avalanche Forecast for Sat Mar 23, 2024
Northern Gallatin, 2024-03-19