

Two skiers were ascending a northeast-facing avalanche path on the northernmost ridgeline of Mount Blackmore around 1 PM when they triggered a large, dry slab avalanche that failed 3 feet deep, 150 feet wide, and ran 500 feet vertical. Debris piled up 4-8 feet deep. One skier was carried to the bottom left of the runout zone. Photo: GNFAC

Advisory Region
Northern Gallatin
Longitude

-111.00W
Latitude
45.44N
Avalanche Details: Skier triggered, caught and injured near Mt Blackmore
Northern Gallatin, 2024-03-19